TALARC CrMo B2 TALARC

Chemwatch Hazard Alert Code: 4

Chemwatch: **5256-73** Version No: **4.1** Safety Data Sheet according to WHS Regulations (Hazardous Chemicals) Amendment 2020 and ADG requirements

Issue Date: 01/11/2019 Print Date: 17/03/2022 L.GHS.AUS.EN.E

SECTION 1 Identification of the substance / mixture and of the company / undertaking

Product Identifier

Product name	TALARC CrMo B2
Chemical Name	Not Applicable
Synonyms	E8018-B2; 2.5 mm, VAC Pack, Part no. INEB225; 3.2 mm, VAC Pack, Part no. INEB232; 4.0 mm, VAC Pack, Part No. INEB240
Chemical formula	Not Applicable
Other means of identification	Not Available

Relevant identified uses of the substance or mixture and uses advised against

Relevant identified uses	Low alloy basic-coated electrode with 1.25% Cr and 0.5% Mo content to be used for the welding of creep resistant steel. Suitable also for the welding of steels with 0.9% Cr and 0.5% Mo content. It is used in chemical industry and in the ammonia synthesis process, for heat exchangers, boilers, piping and pressure vessels for temperature service up to about 550°C. It will also find applications in the petro-chemical industries, suitable for facing on casting and for casting repairs. for welding fume: In addition to complying with any individual exposure standards for specific contaminants, where current manual welding processes are used, the fume concentration inside the welder's helmet should not exceed 5 mg/m3, when collected in accordance with the appropriate standard (AS 3640, for example). ES* TWA: 5 mg/m3 TLV* TWA: 5 mg/m3 Most welding, even with primitive ventilation, does not produce exposures inside the welding helmet above 5 mg/m3. That which does should be controlled (ACGIH). Inspirable dust concentrations in a worker s breathing zone shall be collected and measured in accordance with AS 3640, for example. Metal content can be analytically determined by OSHA Method ID25 (ICP-AES) after total digestion of filters and dissolution of captured metals. Sampling of the Respirable Dust fraction requires cyclone separator devices (elutriators) and procedures to comply with AS 2985 (for example).
--------------------------	--

Details of the supplier of the safety data sheet

Registered company name	TALARC
Address	10-16 Syme Street Brunswick VIC 3056 Australia
Telephone	+61 3 9388 0588
Fax	+61 3 9388 0710
Website	www.talarc.com.au
Email	sales@talarc.com

Emergency telephone number

Association / Organisation	TALARC
Emergency telephone numbers	+61 3 9388 0588 (Hours 9am-5pm AEST)
Other emergency telephone numbers	Not Available

SECTION 2 Hazards identification

Classification of the substance or mixture

Poisons Schedule	Not Applicable
Classification ^[1]	Carcinogenicity Category 1A, Acute Toxicity (Inhalation) Category 4

Legend:	1. Classified by Chemwatch; 2. Classification drawn from HCIS; 3. Classification drawn from Regulation (EU) No 1272/2008 - Annex VI		
Label elements			
Hazard pictogram(s)			
Signal word	Danger		
Hazard statement(s)			
H350	May cause cancer.		
H332	Harmful if inhaled.		
Precautionary statement	Precautionary statement(s) Prevention		
P201	Obtain special instructions before use.		
P271	Use only outdoors or in a well-ventilated area.		
P280	Wear protective gloves and protective clothing.		
P261	Avoid breathing dust/fumes.		

Precautionary statement(s) Response

P308+P313	313 IF exposed or concerned: Get medical advice/ attention.	
P312	Call a POISON CENTER/doctor/physician/first aider/if you feel unwell.	
P304+P340	IF INHALED: Remove person to fresh air and keep comfortable for breathing.	

Precautionary statement(s) Storage

P405	Store locked up.

Precautionary statement(s) Disposal

P501 Dispose of contents/container to authorised hazardous or special waste collection point in accordance with any local regulation.

SECTION 3 Composition / information on ingredients

Substances

See section below for composition of Mixtures

Mixtures

CAS No	%[weight]	Name
Not Available		low allow steel welding electrode
Not Available		which upon use generates:
Not Available	>60	welding fumes
Not Available		as
1309-37-1.		iron oxide fume
7439-96-5.		manganese fume
69012-64-2		silica welding fumes
Not Available		titanium fume
7440-47-3		chromium fume
7439-98-7		molybdenum fume
Legend:	1. Classified by Chemwatch; 2. Classification drawn from HCIS; 3. Classification drawn from Regulation (EU) No 1272/2008 -	

Annex VI; 4. Classification drawn from C&L; * EU IOELVs available

Description of first aid measures

TALARC CrMo B2

	 Particulate bodies from welding spatter may be removed carefully. DO NOT attempt to remove particles attached to or embedded in eye.
Eye Contact	Lay victim down, on stretcher if available and pad BOTH eyes, make sure dressing does not press on the injured eye by placing thick pads under dressing, above and below the eye.
	Seek urgent medical assistance, or transport to hospital.
	 For "arc eye", i.e. welding flash or UV light burns to the eye:
	Place eye pads or light clean dressings over both eyes.
	 Seek medical assistance.
	For THERMAL burns:
	Do NOT remove contact lens
	Lay victim down, on stretcher if available and pad BOTH eyes, make sure dressing does not press on the injured eye by
	placing thick pads under dressing, above and below the eye.
	Seek urgent medical assistance, or transport to hospital.
	If skin or hair contact occurs:
	Flush skin and hair with running water (and soap if available).
	Seek medical attention in event of irritation.
	For thermal burns:
	Decontaminate area around burn.
	Consider the use of cold packs and topical antibiotics.
	For first-degree burns (affecting top layer of skin)
	Hold burned skin under cool (not cold) running water or immerse in cool water until pain subsides.
	Use compresses if running water is not available.
	Cover with sterile non-adhesive bandage or clean cloth.
	Do NOT apply butter or ointments; this may cause infection.
	Give over-the counter pain relievers if pain increases or swelling, redness, fever occur.
	For second-degree burns (affecting top two layers of skin)
	Cool the burn by immerse in cold running water for 10-15 minutes.
	 Use compresses if running water is not available.
	Do NOT apply ice as this may lower body temperature and cause further damage.
	Do NOT break blisters or apply butter or ointments; this may cause infection.
Skin Contact	Protect burn by cover loosely with sterile, nonstick bandage and secure in place with gauze or tape.
	To prevent shock: (unless the person has a head, neck, or leg injury, or it would cause discomfort):
	▶ Lay the person flat.
	► Elevate feet about 12 inches.
	Elevate burn area above heart level, if possible.
	Cover the person with coat or blanket.
	Seek medical assistance.
	For third-degree burns
	Seek immediate medical or emergency assistance.
	In the mean time:
	Protect burn area cover loosely with sterile, nonstick bandage or, for large areas, a sheet or other material that will not leav
	Separate burned toes and fingers with dry, sterile dressings.
	Do not soak burn in water or apply ointments or butter; this may cause infection.
	To prevent shock see above.
	• For an airway burn, do not place pillow under the person's head when the person is lying down. This can close the airway.
	Have a person with a facial burn sit up.
	Check pulse and breathing to monitor for shock until emergency help arrives.
	If fumes or combustion products are inhaled remove from contaminated area.
	Lay patient down. Keep warm and rested.
	Prostheses such as false teeth, which may block airway, should be removed, where possible, prior to initiating first aid
Inhalation	procedures.
	Apply artificial respiration if not breathing, preferably with a demand valve resuscitator, bag-valve mask device, or pocket
	mask as trained. Perform CPR if necessary.
	Transport to hospital, or doctor.
	Not normally a hazard due to physical form of product.

Indication of any immediate medical attention and special treatment needed

Copper, magnesium, aluminium, antimony, iron, manganese, nickel, zinc (and their compounds) in welding, brazing, galvanising or smelting operations all give rise to thermally produced particulates of smaller dimension than may be produced if the metals are divided mechanically. Where insufficient ventilation or respiratory protection is available these particulates may produce "metal fume fever" in workers from an acute or long term exposure.

- Onset occurs in 4-6 hours generally on the evening following exposure. Tolerance develops in workers but may be lost over the weekend. (Monday Morning Fever)
- Pulmonary function tests may indicate reduced lung volumes, small airway obstruction and decreased carbon monoxide diffusing capacity but these abnormalities resolve after several months.
- + Although mildly elevated urinary levels of heavy metal may occur they do not correlate with clinical effects.
- The general approach to treatment is recognition of the disease, supportive care and prevention of exposure.

- TALARC CrMo B2
- Seriously symptomatic patients should receive chest x-rays, have arterial blood gases determined and be observed for the development of tracheobronchitis and pulmonary edema.

[Ellenhorn and Barceloux: Medical Toxicology]

Both dermal and oral toxicity of manganese salts is low because of limited solubility of manganese. No known permanent pulmonary sequelae develop after acute manganese exposure. Treatment is supportive.

[Ellenhorn and Barceloux: Medical Toxicology]

In clinical trials with miners exposed to manganese-containing dusts, L-dopa relieved extrapyramidal symptoms of both hypo kinetic and dystonic patients. For short periods of time symptoms could also be controlled with scopolamine and amphetamine. BAL and calcium EDTA prove ineffective.

[Gosselin et al: Clinical Toxicology of Commercial Products.]

For carbon monoxide intoxications:

- Administer pure oxygen by the best means possible. An oro-nasal mask is usually best. Artificial respiration is necessary wherever breathing is inadequate. Apnoeic patients have often been saved by persistent and efficient artificial ventilation. A patent airway must be carefully maintained. Patients with 40% carboxyhaemoglobin or more and an uncompensated metabolic acidosis (arterial pH less than 7.4) should be managed aggressively with ventilatory support/ hyperbaric oxygenation.
- Gastric aspiration and lavage early in the course of therapy may prevent aspiration pneumonitis and reveal the presence of ingested intoxicants.
- Avoid stimulant drugs including carbon dioxide. DO NOT inject methylene blue.
- ▶ Hypothermia has been employed to reduce the patient's oxygen requirement.
- Consider antibiotics as prophylaxis against pulmonary infection.
- A whole blood transfusion may be useful if it can be given early in the treatment program.
- Infuse sodium bicarbonate and balanced electrolyte solutions if blood analyses indicate a significant metabolic acidosis.
- Ancillary therapy for brain oedema may be necessary if hypoxia has been severe.
- Ensure absolute rest in bed for at least 48 hours; in severe poisonings, 2 to 4 weeks in bed may prevent sequelae.

Watch for late neurological, psychiatric and cardiac complications. GOSSELIN, SMITH HODGE: Clinical Toxicology of Commercial Products 5th Ed. BIOLOGICAL EXPOSURE INDEX (BEI)

These represent the determinants observed in specimens collected from a healthy worker exposed at the Exposure Standard (ES or TLV):

Determinant	Sampling time	Index	Comments
Carboxyhaemoglobin in blood	end of shift	3.5% of haemoglobin	B, NS
Carbon monoxide in end-exhaled air	end of shift	20 ppm	B, NS
B: Background levels occur in specimens collected from subjects NOT exposed			

NS: Non-specific determinant; also observed after exposure to other material

SECTION 5 Firefighting measures

Extinguishing media

- There is no restriction on the type of extinguisher which may be used.
- Use extinguishing media suitable for surrounding area.

Special hazards arising from the substrate or mixture

Fire Incompatibility	Welding electrodes should not be allowed to come into contact with strong acids or other substances which are corrosive to
	metals.

Advice for firefighters

Fire Fighting	 Alert Fire Brigade and tell them location and nature of hazard. Wear breathing apparatus plus protective gloves in the event of a fire. Prevent, by any means available, spillage from entering drains or water courses. Use fire fighting procedures suitable for surrounding area. DO NOT approach containers suspected to be hot. Cool fire exposed containers with water spray from a protected location. If safe to do so, remove containers from path of fire. Equipment should be thoroughly decontaminated after use. Slight hazard when exposed to heat, flame and oxidisers.
Fire/Explosion Hazard	 Welding arc and metal sparks can ignite combustibles. Non combustible. Not considered to be a significant fire risk, however containers may burn. In a fire may decompose on heating and produce toxic / corrosive fumes.
HAZCHEM	Not Applicable

SECTION 6 Accidental release measures

Page 5 of 19 TALARC CrMo B2

See section 8

Environmental precautions

See section 12

Methods and material for containment and cleaning up

Minor Spills	Clean up all spills immediately. Wear impervious gloves and safety glasses. Use dry clean up procedures and avoid generating dust. Place in suitable containers for disposal. Place spilled material in clean, dry, sealable, labelled container.
Major Spills	 Minor hazard. Clear area of personnel. Alert Fire Brigade and tell them location and nature of hazard. Control personal contact with the substance, by using protective equipment if risk of overexposure exists. Prevent, by any means available, spillage from entering drains or water courses. Contain spill/secure load if safe to do so. Bundle/collect recoverable product and label for recycling. Collect remaining product and place in appropriate containers for disposal. Clean up/sweep up area. Water may be required. If contamination of drains or waterways occurs, advise emergency services.

Personal Protective Equipment advice is contained in Section 8 of the SDS.

SECTION 7 Handling and storage

Precautions for safe handling

Safe handling	 Avoid all personal contact, including inhalation. Wear protective clothing when risk of exposure occurs. Use in a well-ventilated area. Prevent concentration in hollows and sumps. DO NOT enter confined spaces until atmosphere has been checked. DO NOT allow material to contact humans, exposed food or food utensils. Avoid contact with incompatible materials. When handling, DO NOT eat, drink or smoke. Keep containers securely sealed when not in use. Avoid physical damage to containers. Always wash hands with soap and water after handling. Work clothes should be laundered separately. Launder contaminated clothing before re-use. Use good occupational work practice. Observe manufacturer's storage and handling recommendations contained within this SDS. Atmosphere should be regularly checked against established exposure standards to ensure safe working conditions are maintained.
Other information	 Keep dry. Store under cover. Protect containers against physical damage. Observe manufacturer's storage and handling recommendations contained within this SDS.

Conditions for safe storage, including any incompatibilities

Suitable container	 Packaging as recommended by manufacturer. Check that containers are clearly labelled
Storage incompatibility	Welding electrodes should not be allowed to come into contact with strong acids or other substances which are corrosive to metals.

SECTION 8 Exposure controls / personal protection

Control parameters

Occupational Exposure Limits (OEL)

INGREDIENT DATA

Source	Ingredient	Material name	TWA	STEL	Peak	Notes
Australia Exposure Standards	welding fumes	Welding fumes (not otherwise classified)	5 mg/m3	Not Available	Not Available	Not Available

Chemwatch: 5256-73
Version No: 4.1

Source	Ingredient	Material name	TWA	STEL	Peak	Notes
Australia Exposure Standards	iron oxide fume	Iron oxide fume (Fe2O3) (as Fe)	5 mg/m3	Not Available	Not Available	Not Available
Australia Exposure Standards	manganese fume	Manganese, fume (as Mn)	1 mg/m3	3 mg/m3	Not Available	Not Available
Australia Exposure Standards	chromium fume	Chromium (metal)	0.5 mg/m3	Not Available	Not Available	Not Available

Emergency Limits

Ingredient	TEEL-1	TEEL-2	TEEL-3
iron oxide fume	15 mg/m3	360 mg/m3	2,200 mg/m3
manganese fume	3 mg/m3	5 mg/m3	1,800 mg/m3
silica welding fumes	45 mg/m3	500 mg/m3	3,000 mg/m3
chromium fume	1.5 mg/m3	17 mg/m3	99 mg/m3
molybdenum fume	30 mg/m3	330 mg/m3	2,000 mg/m3

Ingredient	Original IDLH	Revised IDLH
welding fumes	Not Available	Not Available
iron oxide fume	2,500 mg/m3	Not Available
manganese fume	500 mg/m3	Not Available
silica welding fumes	Not Available	Not Available
chromium fume	250 mg/m3	Not Available
molybdenum fume	Not Available	Not Available

Occupational Exposure Banding

Ingredient	Occupational Exposure Band Rating	Occupational Exposure Band Limit
molybdenum fume	E	≤ 0.01 mg/m³
Notes:	Occupational exposure banding is a process of assigning chemica potency and the adverse health outcomes associated with exposu band (OEB), which corresponds to a range of exposure concentra	ire. The output of this process is an occupational exposure

MATERIAL DATA

Exposure controls

Type of Contaminant: Air Spee	 Controls Controls Corrosion of aluminium) Local exhaust systems must be designed to provide a minimum capture velocity at the fume source, away from metre/sec. Air contaminants generated in the workplace possess varying "escape" velocities which, in turn, dete "capture velocities" of fresh circulating air required to effectively remove the contaminant. 	Appropriate engineering controls	 The basic types of engineering controls are: Process controls which involve changing the way a job active Enclosure and/or isolation of emission source which keeps at that strategically "adds" and "removes" air in the work environdesigned properly. The design of a ventilation system must remployers may need to use multiple types of controls to presse which regulated ventilation requirements apply for processes which regulated as a minimum. (Open work spaces exceed 3000) For work conducted outdoors and in open work spaces, required as a minimum. (Open work spaces exceed 3000) For indoor work, conducted in limited or confined work smandatory. (In confined spaces always check that oxyge corrosion of aluminium) Local exhaust systems must be designed to provide a minim metre/sec. Air contaminants generated in the workplace post "capture velocities" of fresh circulating air required to effective. 	a selected hazard "physic inment. Ventilation can re- match the particular proce- vent employee overexpos- esult in the generation of the use of mechanical (gr cubic meters per welder) paces, use of mechanica in has not been depleted num capture velocity at th sess varying "escape" ve- rely remove the contamin into moderately still air)	ally" away from the worker and v emove or dilute an air contaminan- ess and chemical or contaminan- sure. aluminium, copper, fluoride, ma eneral exhaust or plenum) ventil ventilation by local exhaust sys by excessive rusting of steel or e fume source, away from the w elocities which, in turn, determine ant. Air Speed: 0.5-1.0 m/s (100-200 f/min.)	nt if t in use. Inganese or ation is tems is snowflake rorker, of 0.5
welding, brazing fumes (released at relatively low velocity into moderately still air) (100-200	welding, brazing fumes (released at relatively low velocity into moderately still air) 0.5-1.0 m/s (100-200 f/min.) Within each range the appropriate value depends on:		Lower end of the range	Upper end of the range	9	
Welding, brazing fumes (released at relatively low velocity into moderately still air) (100-200 Within each range the appropriate value depends on:	welding, brazing fumes (released at relatively low velocity into moderately still air) 0.5-1.0 m/s (100-200 f/min.) Within each range the appropriate value depends on:		Lower end of the range	Upper end of the range	9	
	0.5.1.0 m/c			into moderately still air)	(100-200 f/min.)	
exhaust systems must be designed to provide a minimum capture velocity at the fume sources. Air contaminants generated in the workplace possess varying "escape" velocities where the sources were appreciated on the workplace possess varying "escape" velocities where the sources are appreciated on the workplace possess varying "escape" velocities where the sources are appreciated on the workplace possess varying "escape" velocities where the sources are appreciated on the workplace possess varying "escape" velocities where the sources are appreciated on the workplace possess varying "escape" velocities where the sources are appreciated on the workplace possess varying "escape" velocities where the sources are appreciated on the workplace possess varying "escape" velocities where the workplace posses where the sources are appreciated on the workplace possess varying "escape" velocities where the workplace posses where the workpl	andatory. (In commod spaces aways check that oxygen has not been depleted by excessive rusting of ste					
Appropriate engineering controls required as a minimum. (Open work spaces exceed 300 cubic meters per welder) For indoor work, conducted in limited or confined work spaces, use of mechanical ventilation mandatory. (In confined spaces always check that oxygen has not been depleted by excessi corrosion of aluminium) Local exhaust systems must be designed to provide a minimum capture velocity at the fume sou metre/sec. Air contaminants generated in the workplace possess varying "escape" velocities who	engineering required as a minimum. (Open work spaces exceed 300 cubic meters per welder) For indoor work, conducted in limited or confined work spaces, use of mechanical ventilation by local exhaust		zinc fume.	C C		U
Appropriate engineering controls zinc fume. • For work conducted outdoors and in open work spaces, the use of mechanical (general exhart required as a minimum. (Open work spaces exceed 300 cubic meters per welder) • For indoor work, conducted in limited or confined work spaces, use of mechanical ventilation mandatory. (In confined spaces always check that oxygen has not been depleted by excessing corrosion of aluminium) Local exhaust systems must be designed to provide a minimum capture velocity at the fume sour metre/sec. Air contaminants generated in the workplace possess varying "escape" velocities who	 For work conducted outdoors and in open work spaces, the use of mechanical (general exhaust or plenum) required as a minimum. (Open work spaces exceed 300 cubic meters per welder) For indoor work, conducted in limited or confined work spaces, use of mechanical ventilation by local exhaust 		Process controls which involve changing the way a job activ Enclosure and/or isolation of emission source which keeps a that strategically "adds" and "removes" air in the work enviro designed properly. The design of a ventilation system must r Employers may need to use multiple types of controls to pre	a selected hazard "physic inment. Ventilation can re natch the particular proce vent employee overexpos	ally" away from the worker and worker or dilute an air contamina ess and chemical or contaminan sure.	nt if t in use.
Appropriate engineering controls For work conducted outdoors and in open work spaces, the use of mechanical (general exharmed as a minimum. (Open work spaces exceed 300 cubic meters per welder) • For indoor work, conducted in limited or confined work spaces, use of mechanical ventilation well in the spaces always check that oxygen has not been depleted by excessi corrosion of aluminium) Local exhaust systems must be designed to provide a minimum capture velocity at the fume sou metre/sec. Air contaminants generated in the workplace possess varying "escape" velocities wh	 Process controls which involve changing the way a job activity or process is done to reduce the risk. Enclosure and/or isolation of emission source which keeps a selected hazard "physically" away from the worker that strategically "adds" and "removes" air in the work environment. Ventilation can remove or dilute an air contrad designed properly. The design of a ventilation system must match the particular process and chemical or contrant Employers may need to use multiple types of controls to prevent employee overexposure. Special ventilation requirements apply for processes which result in the generation of aluminium, copper, fluoride zinc fume. For work conducted outdoors and in open work spaces, the use of mechanical (general exhaust or plenum) required as a minimum. (Open work spaces exceed 300 cubic meters per welder) For indoor work, conducted in limited or confined work spaces, use of mechanical ventilation by local exhaust 		engineering controls can be highly effective in protecting wo provide this high level of protection.	rkers and will typically be	ker and the hazard. Well-design independent of worker interaction	

TALARC CrMo B2

3: Intermittent, low production.	3: High production, heavy use
4: Large hood or large air mass in motion	4: Small hood-local control only
generally decreases with the square of distance from extraction point should be adjusted, accordingly, after extraction fan, for example, should be a minimum of 1 generated 2 meters distant from the extraction point. I extraction apparatus, make it essential that theoretical systems are installed or used.	distance away from the opening of a simple extraction pipe. Velocity the extraction point (in simple cases). Therefore the air speed at the reference to distance from the contaminating source. The air velocity at the I-2 m/s (200-400 f/min.) for extraction of welding or brazing fumes Other mechanical considerations, producing performance deficits within the I air velocities are multiplied by factors of 10 or more when extraction ion, generally don't require engineering controls during handling or in
	osequent wear, during recycling or disposal operations where substances,
found in the article, may be released to the environme	
u	place a barrier between the worker and the hazard. Well-designed
provide this high level of protection.	ing workers and will typically be independent of worker interactions to
The basic types of engineering controls are:	
Process controls which involve changing the way a jo	b activity or process is done to reduce the risk.
	ceeps a selected hazard "physically" away from the worker and ventilation
U	environment. Ventilation can remove or dilute an air contaminant if
designed properly. The design of a ventilation system Employers may need to use multiple types of controls	must match the particular process and chemical or contaminant in use.

Special ventilation requirements apply for processes which result in the generation of barium, chromium, lead, or nickel fume and in those processes which generate ozone.

The use of mechanical ventilation by local exhaust systems is required as a minimum in all circumstances (including outdoor work). (In confined spaces always check that oxygen has not been depleted by excessive rusting of steel or snowflake corrosion of aluminium)

Local exhaust systems must be designed to provide a minimum capture velocity at the fume source, away from the worker, of 0.5 metre/sec. Air contaminants generated in the workplace possess varying "escape" velocities which, in turn, determine the "capture velocities" of fresh circulating air required to effectively remove the contaminant.

Type of Contaminant:	Air Speed:
welding, brazing fumes (released at relatively low velocity into moderately still air)	0.5-1.0 m/s (100-200 f/min.)
Within each range the appropriate value depends on:	

Lower end of the range	Upper end of the range
1: Room air currents minimal or favourable to capture	1: Disturbing room air currents
2: Contaminants of low toxicity or of nuisance value only.	2: Contaminants of high toxicity
3: Intermittent, low production.	3: High production, heavy use
4: Large hood or large air mass in motion	4: Small hood-local control only

Simple theory shows that air velocity falls rapidly with distance away from the opening of a simple extraction pipe. Velocity generally decreases with the square of distance from the extraction point (in simple cases). Therefore the air speed at the extraction point should be adjusted, accordingly, after reference to distance from the contaminating source. The air velocity at the extraction fan, for example, should be a minimum of 1-2 m/s (200-400 f/min.) for extraction of welding or brazing fumes generated 2 meters distant from the extraction point. Other mechanical considerations, producing performance deficits within the extraction apparatus, make it essential that theoretical air velocities are multiplied by factors of 10 or more when extraction systems are installed or used.

For manual arc welding operations the nature of ventilation is determined by the location of the work.

- For outdoor work, natural ventilation is generally sufficient.
- + For indoor work, conducted in open spaces, use mechanical (general exhaust or plenum) ventilation. (Open work spaces exceed 300 cubic metres per welder)
- For work conducted in limited or confined spaces, mechanical ventilation, using local exhaust systems, is required. (In confined spaces always check that oxygen has not been depleted by excessive rusting of steel or snowflake corrosion of aluminium)

Mechanical or local exhaust ventilation may not be required where the process working time does not exceed 24 mins. (in an 8 hr. shift) provided the work is intermittent (a maximum of 5 mins. every hour). Local exhaust systems must be designed to provide a minimum capture velocity at the fume source, away from the worker, of 0.5 metre/sec. Air contaminants generated in the workplace possess varying "escape" velocities which, in turn, determine the "capture velocities" of fresh circulating air required to effectively remove the contaminant.

Type of Contaminant:	Air Speed:
welding, brazing fumes (released at relatively low velocity into moderately still air)	0.5-1.0 m/s (100-200 f/min.)
Within each range the appropriate value depends on:	

Lower end of the range

TALARC CrMo B2

	1: Room air currents minimal or favourable to capture	1: Disturbing room air currents	
	2: Contaminants of low toxicity or of nuisance value only.	2: Contaminants of high toxicity	
	3: Intermittent, low production.	3: High production, heavy use	
	4: Large hood or large air mass in motion	4: Small hood-local control only	
	extraction point should be adjusted, accordingly, after referer extraction fan, for example, should be a minimum of 1-2.5 m distant from the extraction point. Other mechanical considera apparatus, make it essential that theoretical air velocities are installed or used. Engineering controls are used to remove a hazard or place a engineering controls can be highly effective in protecting wor provide this high level of protection. The basic types of engineering controls are: Process controls which involve changing the way a job activi Enclosure and/or isolation of emission source which keeps a that strategically "adds" and "removes" air in the work enviro designed properly. The design of a ventilation system must n Employers may need to use multiple types of controls to prev Local exhaust ventilation usually required. If risk of overexpo obtain adequate protection. An approved self contained breathing apparatus (SCBA) ma	/s (200-500 f/min.) for extraction of gases d ations, producing performance deficits withi multiplied by factors of 10 or more when e a barrier between the worker and the hazard kers and will typically be independent of wo ty or process is done to reduce the risk. selected hazard "physically" away from the nment. Ventilation can remove or dilute an natch the particular process and chemical of yent employee overexposure. sure exists, wear approved respirator. Corr be required in special circumstances. Corror y be required in some situations.	ischarged 2 meters in the extraction xtraction systems are d. Well-designed orker interactions to e worker and ventilation air contaminant if or contaminant in use. ect fit is essential to ect fit is essential to
	Provide adequate ventilation in warehouse or closed storage area. Air contaminants generated in the workplace possess varyir "escape" velocities which, in turn, determine the "capture velocities" of fresh circulating air required to effectively remove the contaminant. Type of Contaminant: Air Speed: solvent, vapours, degreasing etc., evaporating from tank (in still air). 0.25-0.5 m/s (50-100 f/min.)		
	aerosols, fumes from pouring operations, intermittent conta welding, spray drift, plating acid fumes, pickling (released a generation)		0.5-1 m/s (100-200 f/min.)
direct spray, spray painting in shallow booths, drum filling, conveyer loading, crusher dusts, gas 1-2.5 m		1-2.5 m/s (200-500 f/min.)	
	grinding, abrasive blasting, tumbling, high speed wheel generated dusts (released at high initial velocity into zone of very high rapid air motion). (500-2000 f/r		2.5-10 m/s (500-2000 f/min.)
	Within each range the appropriate value depends on:		
	Lower end of the range	Upper end of the range	
	1: Room air currents minimal or favourable to capture	1: Disturbing room air currents	
	2: Contaminants of low toxicity or of nuisance value only.	2: Contaminants of high toxicity	
	3: Intermittent, low production.	3: High production, heavy use	
	4: Large hood or large air mass in motion	4: Small hood-local control only	
	Simple theory shows that air velocity falls rapidly with distance generally decreases with the square of distance from the ext extraction point should be adjusted, accordingly, after referer extraction fan, for example, should be a minimum of 1-2 m/s meters distant from the extraction point. Other mechanical co apparatus, make it essential that theoretical air velocities are installed or used.	raction point (in simple cases). Therefore the nee to distance from the contaminating sour (200-400 f/min) for extraction of solvents g onsiderations, producing performance defice	he air speed at the rce. The air velocity at the enerated in a tank 2 its within the extraction
tection			

Welding helmet with suitable filter. Welding hand shield with suitable filter.

Goggles or other suitable eye protection shall be used during all gas welding or oxygen cutting operations. Spectacles without side shields, with suitable filter lenses are permitted for use during gas welding operations on light work, for torch brazing or for inspection.

Eye and face protection For most op

 For most open welding/brazing operations, goggles, even with appropriate filters, will not afford sufficient facial protection for operators. Where possible use welding helmets or handshields corresponding to EN 175, ANSI Z49:12005, AS 1336 and AS 1338 which provide the maximum possible facial protection from flying particles and fragments. [WRIA-WTIA Technical Note 7]

An approved face shield or welding helmet can also have filters for optical radiation protection, and offer additional protection

	 against debris and sparks. UV blocking protective spectacles with side shields or welding goggles are considered primary protection, with the face shield or welding helmet considered secondary protection. The optical filter in welding goggles, face mask or helmet must be a type which is suitable for the sort of work being done. A filter suitable for gas welding, for instance, should not be used for arc welding. Face masks which are self dimming are available for arc welding, MIG, TIG and plasma cutting, and allow better vision before the arc is struck and after it is extinguished. For submerged arc welding use a lens shade which gives just sufficient arc brightness to allow weld pool control.
Skin protection	See Hand protection below
Hands/feet protection	 Welding Gloves Safety footwear Welding gloves conforming to Standards such as EN 12477:2001, ANSI Z49.1, AS/NZS 2161:2008 produced from leather, rubber, treated cotton,or alumininised These gloves protect against mechanical risk caused by abrasion, blade cut, tear and puncture Other gloves which protect against thermal risks (heat and fire) might also be considered - these comply with different standards to those mentioned above. One pair of gloves may not be suitable for all processes. For example, gloves that are suitable for low current Gas Tungsten Arc Welding (GTAW) (thin and flexible) would not be proper for high-current Air Carbon Arc Cutting (CAC-A) (insulated, tough, and durable)
Body protection	See Other protection below
Other protection	Aprons, sleeves, shoulder covers, leggings or spats of pliable flame resistant leather or other suitable materials may also be required in positions where these areas of the body will encounter hot metal. Before starting; consider that protection should be provided for all personnel within 10 metres of any open arc welding operation. Welding sites must be adequately shielded with screens of non flammable materials. Screens should permit ventilation at floor and ceiling levels. Overalls

Respiratory protection

Welding of powder coated metal requires good general area ventilation, and ventilated mask as local heat causes minor coating decomposition releasing highly discomforting fume which may be harmful if exposure is regular.

Welding or flame cutting of metals with chromate pigmented primers or coatings may result in inhalation of highly toxic chromate fumes. Exposures may be significant in enclosed or poorly ventilated areas

Respiratory protection not normally required due to the physical form of the product.

SECTION 9 Physical and chemical properties

Information on basic physical and chemical properties

Appearance	Solid grey welding rod with no odour; shaped as a rod of different diameters, insoluble in water		
Physical state	Manufactured	Relative density (Water = 1)	~5
Odour	Not Available	Partition coefficient n-octanol / water	Not Available
Odour threshold	Not Available	Auto-ignition temperature (°C)	Not Applicable
pH (as supplied)	Not Applicable	Decomposition temperature	Not Available
Melting point / freezing point (°C)	~1500	Viscosity (cSt)	Not Applicable
Initial boiling point and boiling range (°C)	Not Applicable	Molecular weight (g/mol)	Not Applicable
Flash point (°C)	Not Applicable	Taste	Not Available
Evaporation rate	Not Applicable	Explosive properties	Not Available
Flammability	Not Applicable	Oxidising properties	Not Available
Upper Explosive Limit (%)	Not Applicable	Surface Tension (dyn/cm or mN/m)	Not Applicable
Lower Explosive Limit (%)	Not Applicable	Volatile Component (%vol)	Not Applicable
Vapour pressure (kPa)	Not Applicable	Gas group	Not Available
Solubility in water	Immiscible	pH as a solution (Not Available%)	Not Applicable
Vapour density (Air = 1)	Not Available	VOC g/L	Not Applicable

SECTION 10 Stability and reactivity

Reactivity	See section 7
Chemical stability	Product is considered stable and hazardous polymerisation will not occur.
Possibility of hazardous reactions	See section 7
Conditions to avoid	See section 7
Incompatible materials	See section 7
Hazardous decomposition products	See section 5

SECTION 11 Toxicological information

protective clothing.

Information on toxicological effects

Fumes evolved during welding operations may be irritating to the upper-respiratory tract and may be harmful if inhaled.

Inhalation of freshly formed metal oxide particles sized below 1.5 microns and generally between 0.02 to 0.05 microns may result in "metal fume fever". Symptoms may be delayed for up to 12 hours and begin with the sudden onset of thirst, and a sweet, metallic or foul taste in the mouth. Other symptoms include upper respiratory tract irritation accompanied by coughing and a dryness of the mucous membranes, lassitude and a generalised feeling of malaise. Mild to severe headache, nausea, occasional vomiting, fever or chills, exaggerated mental activity, profuse sweating, diarrhoea, excessive urination and prostration may also occur. Tolerance to the fumes develops rapidly, but is quickly lost. All symptoms usually subside within 24-36 hours following removal from exposure. Bronchial and alveolar exudate are apparent in animals exposed to molybdenum by inhalation. Molybdenum fume may produce bronchial irritation and moderate fatty changes in liver and kidney. Acute carbon monoxide exposure can mimic acute gastroenteritis or food poisoning with accompanying nausea and vomiting. Rapidly fatal cases of poisoning are characterised by congestion and hemorrhages in all organs. The extent of the tissue and organ damage is related to the duration of the post-hypoxic unconsciousness. Exposure to carbon monoxide can result in immediate effects and, depending on the severity of the exposure, delayed effects. These delayed effects may occur days to weeks after the initial exposure. Signs of brain or nerve injury may appear at any time within three weeks following an acute exposure. Characteristically, those patients manifesting delayed neuropathology are middle aged or older. Most of the neurological symptoms associated with carbon monoxide exposure can resolve within a year but memory deficits and gait disturbances may remain Symptoms of poisoning resulting from carbon monoxide exposure include respiratory disorders, diarrhoea and shock. Carbon monoxide competes with oxygen for haemoglobin binding sites and has a 240-fold affinity for these sites compared to oxygen. In addition to oxygen deficiency further disability is produced by the formation of carboxymyoglobin (COHb) in muscles, to produce Inhaled disturbances in muscle metabolism, particularly that of the heart. The tissues most affected by carbon monoxide are those which are most sensitive to oxygen deprivation such as the brain and the heart. The overt lesion in these tissues is mostly haemorrhage. The severe headache associated with exposure is believed to be caused by cerebral oedema and increased intracranial pressure resulting from excessive transudate leakage of fluids through the hypoxic capillaries. Carbon monoxide induced hypoxia in the cochlea and brain stem leads to central hearing loss and vestibular dysfunction (vertigo, nausea, vomiting) with the vestibular symptoms usually more prominent than the hearing loss At low levels carbon monoxide may cause poor concentration, memory and vision problems, vertigo, muscular weakness and loss of muscle coordination, rapid and stretorous breathing, intermittent heart beat, loss of sphincter control and rarely coma and death. At higher levels (200 ppm for 2-3 hours), it may cause headaches, fatigue and nausea. At very high levels (400 ppm) the symptoms intensify and will be life-threatening after three hours. Exposure to levels of 1200 ppm or greater are immediately dangerous to life. When carbon monoxide levels in air exceed 3% (30,000 ppm), death occurs almost at once. Carbon monoxide is not a cumulative poison since COHb is fully dissociable and once exposure has ceased, the hemoglobin will revert to oxyhemoglobin. The biological half life of carbon monoxide in the blood in sedentary adults is 2-5 hours and the elimination becomes slower as the concentration decreases. Manganese fume is toxic and produces nervous system effects characterised by tiredness. Acute poisoning is rare although acute inflammation of the lungs may occur. A chemical pneumonia may also result from frequent exposure. Inhalation of freshly formed metal oxide particles sized below 1.5 microns and generally between 0.02 to 0.05 microns may result in "metal fume fever". Symptoms may be delayed for up to 12 hours and begin with the sudden onset of thirst, and a sweet, metallic or foul taste in the mouth. Other symptoms include upper respiratory tract irritation accompanied by coughing and a dryness of the mucous membranes, lassitude and a generalised feeling of malaise. Mild to severe headache, nausea, occasional vomiting, fever or chills, exaggerated mental activity, profuse sweating, diarrhoea, excessive urination and prostration may also occur. Tolerance to the fumes develops rapidly, but is quickly lost. All symptoms usually subside within 24-36 hours following removal from exposure. Ingestion Not normally a hazard due to physical form of product. Skin contact does not normally present a hazard, though it is always possible that occasionally individuals may be found who react to substances usually regarded as inert. Ultraviolet radiation (UV) is generated by the electric arc in the welding process. Skin exposure to UV can result in severe burns, in many cases without prior warning. Skin Contact Exposure to infrared radiation (IR), produced by the electric arc and other flame cutting equipment may heat the skin surface and the tissues immediately below the surface. Except for this effect, which can progress to thermal burns in some situations, infrared radiation is not dangerous to welders. Most welders protect themselves from IR (and UV) with a welder's helmet (or glasses) and

Eye	Fumes from welding/brazing operations may be irritating to the eyes. Ultraviolet (UV) radiation can also damage the lens of the eye. Many arc welders are aware of the condition known as "arc-eye," a sensation of sand in the eyes. This condition is caused by excessive eye exposure to UV. Exposure to ultraviolet rays may also increase the skin effects of some industrial chemicals (coal tar and cresol compounds, for example). Exposure of the human eye to intense visible light can produce adaptation, pupillary reflex, and shading of the eyes. Such actions are protective mechanisms to prevent excessive light from being focused on the retina. In the arc welding process, eye exposure to intense visible light is prevented for the most part by the welder's helmet. However, some individuals have sustained retinal damage due to careless "viewing" of the arc. At no time should the arc be observed without eye protection.
Chronic	On the basis, primarity, or animal experiments, concern has been expressed that the material may produce carcinogenic or making a satisfactory assessment. Repeated or prolonged exposure may also damage the liver and may cause a decrease in the heart rate. Systemic poisoning may result from inhalation or chronic ingestion of manganese containing substances. Progressive and permanent disability can occur from chronic manganese poisoning if it is not retade, but it is not fatal. Chronic exposure has been associated with two major effects, bronchrits/pneumonils following inhalation of manganese dusts and "manganism", a neuropsychiatric disorder that may also arise from inhalation exposure to low levels may result in the accumulation of toxic concentrations in critical organs. The brain in particular appears to sustain cellular damage to the gangtion. Symptoms appear before any pathology is evident and may include a mask. He facial expression, spastic gait, ternors, slurred speech, sometimes dystanic (disordered muscle tone), fatigue, ancresia, asthenia (loss of strength and energy), apathy and the inability to concentrate. Insomin may be an early finding. Chronic poisoning may occur over a 6-24 month period depending on exposure levels. The onset of chronic manganese poisonism is more used to the site assess. Neadoche and spasms. Manganese psycholis follows with certain definite features: unaccurable laughter, exploria, impulsive asts, absentinidedness, mental contalution, aggressiveness and hallucinations. The final stage is characterised by speech difficulties, muscular twiching, spatic gait and other navous system difficult. Symptoms treatmathe thac or Instances, weaken difficulties, muscular twiching, spatic gait and other navous system difficult by comparison. The maxima is a statistical contangenes in any cause metal turne lever characterised by the lever, chill, nausea, weakenes and boly aches. Manganese tas an aggraving factor to a preexisting condition. Proving set to sustain a comparis a statistical set t

S9 metabolic activation enzymes. Pneumoconiosis has been described in experimental animals exposed sub-chronically to molybdenum trioxide. The mechanism of molybdenum trioxide action in lung carcinogenicity is not known; the material is not mutagenic.

Non-neoplastic lesions of the nose and larynx of rats and in the nose, larynx and lungs of mice were apparently due to the development of a more durable epithelium in response to chronic exposure. The US Department of Health and Human Services (1) concluded that there was equivocal evidence of carcinogenic activity in male F344/N rats based on a marginally significant positive trend of alveolar/ bronchiolar adenoma or carcinoma; that there was no evidence of carcinogenic activity in female F344/N rats; that there was some evidence of carcinogenic activity in male B6C3F1 mice and that there was evidence of carcinogenic activity in female Report Series 462, April 1997
Principal route of exposure is inhalation of welding fumes from electrodes and workpiece. Reaction products arising from electrode core and flux appear as welding fume depending on welding conditions, relative volatilities of metal oxides and any coatings on the workpiece. Studies of lung cancer among welders indicate that they may experience a 30-40% increased risk compared to the general population. Since smoking and exposure to other cancer-causing agents, such as asbestos fibre, may influence these results, it is not clear whether welding, in fact, represents a significant lung cancer risk. Whilst mild steel welding represents little risk, the stainless steel welder, exposed to chromium and nickel fume, may be at risk and it is this factor which may account for the overall increase in lung cancer incidence among welders. Cold isolated electrodes are relatively harmless. Long-term (chronic) exposure to low levels of carbon monoxide may produce heart disease and damage to the nervous system. Exposure of pregnant animals to carbon monoxide may cause low birthweight, increased foetal mortality and nervous system damage to the offspring.
Carbon monoxide is a common cause of fatal poisoning in industry and homes. Non fatal poisoning may result in permanent nervous system damage. Carbon monoxide reduces the oxygen carrying capacity of the blood. Effects on the body are considered to be reversible as long as brain cell damage or heart failure has not occurred. Avoid prolonged exposure, even to small concentrations. A well-established and probably causal relationship exists between maternal smoking (resulting in carboxyhaemoglobin levels of 2-7% in the foetus) and low birth weight. There also appears to be a dose-related increase in perinatal deaths and a retardation of mental ability in infants born to smoking mothers. The foetus and newborn infant are considered to be very susceptible to CO exposure for several reasons:
 Foetal hemoglobin has a greater affinity for CO than maternal hemoglobin. Due to differences in uptake and elimination of CO, the fetal circulation is likely to have COHb levels higher (up to 2.5 times) than seen in the maternal circulation. The half-life of COHb in fetal blood is 3 times longer than that of maternal blood. Since the fetus has a comparatively high rate of O2 consumption, and a lower O2 tension in the blood than adults, a compromised O2 transport has the potential to produce a serious hypoxia. Carbon monoxide gas readily crosses the placenta and CO exposure during pregnancy can be teratogenic. Carbon dioxide at low levels may initiate or enhance deleterious myocardial alterations in individuals with restricted coronary artery blood flow and decreased myocardial lactate production Linde Metal oxides generated by industrial processes such as welding, give rise to a number of potential health problems. Particles
 smaller than 5 micron (respirables) articles may cause lung deterioration. Particles of less than 1.5 micron can be trapped in the lungs and, dependent on the nature of the particle, may give rise to further serious health consequences. Exposure to fume containing high concentrations of water-soluble chromium (VI) during the welding of stainless steels in confined spaces has been reported to result in chronic chrome intoxication, dermatitis and asthma. Certain insoluble chromium (VI) compounds have been named as carcinogens (by the ACGIH) in other work environments. Chromium may also appear in welding fumes as Cr2O3 or double oxides with iron. These chromium (III) compounds are generally biologically inert. Welding fume with high levels of ferrous materials may lead to particle deposition in the lungs (siderosis) after long exposure. This clears up when exposure stops. Chronic exposure to iron dusts may lead to eye disorders. Silica and silicates in welding fumes are non-crystalline and believed to be non-harmful. Other welding process exposures can arise from radiant energy UV flash burns, thermal burns or electric shock
The welding are omits utravial tradiction of wavelengths that have the netartial to produce align turgers in animals and in

The welding arc emits ultraviolet radiation at wavelengths that have the potential to produce skin tumours in animals and in over-exposed individuals, however, no confirmatory studies of this effect in welders have been reported.

TALARC CrMo B2	ΤΟΧΙΟΙΤΥ	IRRITATION
	Not Available	Not Available
	ΤΟΧΙΟΙΤΥ	IRRITATION
welding fumes	Not Available	Not Available
	ΤΟΧΙΟΙΤΥ	IRRITATION
iron oxide fume	Oral (Rat) LD50; >5000 mg/kg ^[1]	Not Available
manganese fume	ΤΟΧΙΟΙΤΥ	IRRITATION
	Inhalation(Rat) LC50; >5.14 mg/l4h ^[1]	Eye (rabbit) 500mg/24H Mild
	Oral (Rat) LD50; >2000 mg/kg ^[1]	Eye: no adverse effect observed (not irritating) ^[1]
		Skin (rabbit) 500mg/24H Mild
		Skin: no adverse effect observed (not irritating) $^{[1]}$
	ΤΟΧΙΟΙΤΥ	IRRITATION
silica welding fumes	Dermal (rabbit) LD50: >5000 mg/kg ^[2]	Eye: no adverse effect observed (not irritating) ^[1]
	Oral (Rat) LD50; 3160 mg/kg ^[2]	Skin: no adverse effect observed (not irritating) ^[1]

	ΤΟΧΙΟΙΤΥ	IRRITATION	
chromium fume	Inhalation(Rat) LC50; >5.41 mg/l4h ^[1]	Not Available	
	Oral (Rat) LD50; >5000 mg/kg ^[1]		
	тохісіту	IRRITATION	
makekalan una funa a	dermal (rat) LD50: >2000 mg/kg ^[1]	Not Available	
molybdenum fume	Inhalation(Rat) LC50; >1.93 mg/l4h ^[1]		
	Oral (Rat) LD50; >2000 mg/kg ^[1]		
Legend:	 Value obtained from Europe ECHA Registered Substances - Acute toxicity 2.* Value obtained from manufacturer's SDS. Unless otherwise specified data extracted from RTECS - Register of Toxic Effect of chemical Substances 		
WELDING FUMES	Most welding is performed using electric arc processes - manual metal arc, metal inert gas (MIG) and tungsten inert gas weld (TIG) – and most welding is on mild steel. In 2017, an IARC working group has determined that "sufficient evidence exists that welding fume is a human lung carcinoger (Group 1). A complicating factor in classifying welding fumes is its complexity. Generally, welding fume is a mixture of metal fumes (i.e., i manganese, chromium, nickel, silicon, titanium) and gases (i.e., carbon monoxide, ozone, argon, carbon dioxide). Welding fur can contain varying concentrations of individual components that are classified as human carcinogens, including hexavalent tchrome and nickel. However the presence of such metals and the intensity of exposure to each differ significantly according to number of variables, including the type of welding technique used and the composition of the base metal and consumable. Nonetheless, IARC did not differentiate between these variables in its decision. There has been considerable evidence over several decades regarding cancer risks in relation to welding activities. Several case-control studies reported excess risks of ocular melanoma in welders. This association may be due to the presence in so welding environments may present different nato complex profiles of exposures. In one study to characterise welding furme aerosol nanoparticles in mild steel metal active gas welding showed a mass median diameter (MMMD) of 200-300 mm, widespread consensus seems to have formed to the effect that some welding environments, motably in stainless steel welding unitial welding without the presence of nickel and chromium VI compounds, namely mild-steel welding, should not carry risk. But it appears that this line of reasoning in not supported by 1 accumulated body of epidemiologic evidence. While there remained some uncertainty about possible confounding by smoking and by asbestos, and some possible publication bias, the overwhelming evidence is that there has been an excess risk of		

Personal exposures to manganese ranged from 0.01-4.93 mg/m3 and to iron ranged from 0.04-16.29 mg/m3 in eight Canadian welding companies. Types of welding identified were mostly (90%) MIG mild steel, MIG stainless steel, and TIG aluminum. Carbon monoxide levels were less than 5.0 ppm (at source) and ozone levels varied from 0.4-0.6 ppm (at source). Welders, especially in shipyards, may also be exposed to asbestos dust. Physical exposures such as electric and magnetic fields (EMF) and ultraviolet (UV) radiation are also common.

In all, the in vivo studies suggest that different welding fumes cause varied responses in rat lungs in vivo, and the toxic effects typically correlate with the metal composition of the fumes and their ability to produce free radicals. In many studies both soluble and insoluble fractions of the stainless steel welding fumes were required to produce most types of effects, indicating that the responses are not dependent exclusively on the soluble metals

Lung tumourigenicity of welding fumes was investigated in lung tumour susceptible (A/J) strain of mice. Male mice were exposed by pharyngeal aspiration four times (once every 3 days) to 85 ug of gas metal arc-mild steel (GMA-MS),

GMA-SS, or manual metal arc-SS (MMA-SS) fume. At 48 weeks post-exposure, GMA-SS caused the greatest increase in tumour multiplicity and incidence, but did not differ from sham exposure. Tumour incidence in the GMA-SS group versus sham control was close to significance at 78 weeks post exposure. Histopathological analysis of the lungs of these mice showed the GMA-SS group having an increase in preneoplasia/tumour multiplicity and incidence compared to the GMA-MS and sham groups at 48 weeks. The increase in incidence in the GMA-SS exposed mice was significant compared to the GMA-MS group but not to the sham-exposed animals, and the difference in incidence between the GMA-SS and MMA-SS groups was of border-line

	significance (p = 0.06). At 78 week s post-exposure, no statistically significant differences A significantly higher frequency of micronuclei in peripheral blood lymphocytes (binucleated cell assay) and higher mean levels of both centromere-positive and centromere-negative micronuclei was observed in welders (n=27) who worked without protective device compared to controls (n=30). The rate of micronucleated cells did not correlate with the duration of exposure WARNING: This substance has been classified by the IARC as Group 1: CARCINOGENIC TO HUMANS . Not available. Refer to individual constituents.
SILICA WELDING FUMES	Not available. Refer to individual constituents. For silica amorphous: Derived No Adverse Effects Level (NOAEL) in the range of 1000 mg/kg/d. In humans, synthetic amorphous silica (SAS) is essentially non-toxic by mouth, skin or eyes, and by inhalation. Epidemiology studies show little evidence of adverse health effects due to SAS. Repeated exposure (without personal protection) may cause mechanical inflation of the eye and driving/cracking of the skin. When experimental animals indule synthetic amorphous silica (SAS) dust, it dissolves in the lung fluid and is rapidly eliminated. If swallowed, the vast majority of SAS is excreted in the faces and there is little accumulation in the body. Following absorption across the gut, SAS is eliminated via urine without modification in animals and humans. SAS is not expected to be broken down (metabolised) in mammals. After ingestion, there is limited accumulation of SAS in body tissues and rapid elimination occurs. Intestinal absorption has not been acculated, but appears to be insignificant in animals and humans. SASs in jineled subcultaneously are subjected to rapid dissolution and removal. There is no indication of metabolism of SAS in animals or humans based on chemical species that are formed are eliminated via the urinary tract without modificantly influenced by the physical and chemical properties, particularly those of solubility and particle size. SAS has no acute intrinsic toxicity by inhalation. Adverse effects, including suffocation, that have been reported were caused by the presence of high numbers of respirable particles generated to meet the required test atmosphere. These results are not representative of exposure to commercial SASs and should not be used for human ink assessment. Though repeated exposure. Long-term inhalation of SAS caused some adverse effects in animals (increases in lung inflammation, cell injury and lung collagen content), all of which subided after exposure. Numerous repeated-dose, subchronic and Atimatin toxici
CHROMIUM FUME	For chrome(III) and other valence states (except hexavalent): For inhalation exposure, all trivalent and other chromium compounds are treated as particulates, not gases. The mechanisms of chromium toxicity are very complex, and although many studies on chromium are available, there is a great deal of uncertainty about how chromium exerts its toxic influence. Much more is known about the mechanisms of hexavalent chromium toxicity than trivalent chromium toxicity. There is an abundance of information available on the carcinogenic potential of chromium compounds and on the genotoxicity and mutagenicity of chromium compounds in experimental systems. The consensus from various reviews and agencies is that evidence of carcinogenicity of elemental, divalent, or trivalent chromium compounds is lacking. Epidemiological studies of workers in a number of industries (chromate production, chromate pigment production and use, and chrome plating) conclude that while occupational exposure to hexavalent chromium compounds is associated with an increased risk of respiratory system cancers (primarily bronchogenic and nasal), results from occupational exposure studies to mixtures that were mainly elemental and trivalent (ferrochromium alloy worker) were inconclusive. Studies in leather tanners, who were exposed to trivalent chromium were consistently negative. In addition to the lack of direct evidence of carcinogenicity of trivalent or elemental chromium and its compounds, the genotoxic evidence is overwhelmingly negative. The lesser potency of trivalent chromium relative to hexavalent chromium is likely related to the higher redox potential of hexavalent formoium and its greater ability to enter cells The general inability of trivalent chromium to traverse membranes and thus be absorbed or reach peripheral tissue in significant amounts is generally accepted as a probable explanation for the overall absence of systemic trivalent chromium toxicity. Elemental and divalent forms of chromium are not able to traverse membranes readily

	are permeable across nonselective membranes. Trivalent chromium forms octahedral complexes which cannot easily enter though these channels, instead being absorbed via passive diffusion and phagocytosis. Although trivalent chromium is less wel absorbed than hexavalent chromium, workers exposed to trivalent compounds have had detectable levels of chromium in the urine at the end of a workday. Absorbed chromium is widely distributed throughout the body via the bloodstream, and can reach the foetus. Although there is ample in vivo evidence that hexavalent chromium is efficiently reduced to trivalent chromium in the gastrointestinal tract and can be reduced to the trivalent form by ascorbate and glutathione in the lungs, there is no evidence the trivalent chromium is biological systems. In general, trivalent chromium compounds are cleared rapidly from the blood and more slowly from the tissues. Although not fully characterized, the biologically active trivalen chromium molecule appears to be chromodulin, also referred to as (GTF). Chromodulin is an oligopeptide complex containing four chromic ions. Chromodulin may facilitate interactions of insulin with its receptor site, influencing protein, glucose, and lipid metabolism. Inorganic trivalent chromium compounds, which do not appear to have insulin-potentiating properties, are capable being converted into biologically active forms by humans and animals Chromium can be a potent sensitiser in a small minority of humans, both from dermal and inhalation exposures. The most sensitive endpoint identified in animal studies of acute exposure to trivalent chromium appears to involve the respiratory system. Specifically, acute exposure to trivalent chromium is associated with impaired lung function and lung damage Based on what is known about absorption of chromium in the human body, its potential mechanism of action in cells, and occupational data indicating that valence states other than hexavalent exhibit a relative lack of toxicity the toxicity of elemental and divalent ch			
MOLYBDENUM FUME	Asthma-like symptoms may continue for months or even years after exposure to the material ceases. This may be due to a non-allergenic condition known as reactive airways dysfunction syndrome (RADS) which can occur following exposure to high levels of highly irritating compound. Key criteria for the diagnosis of RADS include the absence of preceding respiratory disease, in a non-atopic individual, with abrupt onset of persistent asthma-like symptoms within minutes to hours of a documented exposure to the irritant. A reversible airflow pattern, on spirometry, with the presence of moderate to severe bronchial hyperreactivity on methacholine challenge testing and the lack of minimal lymphocytic inflammation, without eosinophilia, have also been included in the criteria for diagnosis of RADS. RADS (or asthma) following an irritating inhalation is an infrequent disorder with rates related to the concentration of and duration of exposure to the irritating substance. Industrial bronchitis, on the other hand, is a disorder that occurs as result of exposure due to high concentrations of irritating substance (often particulate in nature) and is completely reversible after exposure ceases. The disorder is characterised by dyspnea, cough and mucus			
	also been included in the criteria for diagnosis of disorder with rates related to the concentration other hand, is a disorder that occurs as result of nature) and is completely reversible after expos	ng and the lack of minimal lympho of RADS. RADS (or asthma) follow of and duration of exposure to the f exposure due to high concentrat	cytic inflammation, without eosinophilia, have ving an irritating inhalation is an infrequent irritating substance. Industrial bronchitis, on the ions of irritating substance (often particulate in	
SILICA WELDING FUMES & CHROMIUM FUME	also been included in the criteria for diagnosis of disorder with rates related to the concentration other hand, is a disorder that occurs as result of	ng and the lack of minimal lympho of RADS. RADS (or asthma) follow of and duration of exposure to the f exposure due to high concentrati ure ceases. The disorder is chara 3: hans.	cytic inflammation, without eosinophilia, have ving an irritating inhalation is an infrequent irritating substance. Industrial bronchitis, on the ions of irritating substance (often particulate in	
SILICA WELDING FUMES	also been included in the criteria for diagnosis of disorder with rates related to the concentration of other hand, is a disorder that occurs as result of nature) and is completely reversible after exposi- production. The substance is classified by IARC as Group 3 NOT classifiable as to its carcinogenicity to hum	ng and the lack of minimal lympho of RADS. RADS (or asthma) follow of and duration of exposure to the f exposure due to high concentrati ure ceases. The disorder is chara 3: nans. or limited in animal testing.	cytic inflammation, without eosinophilia, have ving an irritating inhalation is an infrequent irritating substance. Industrial bronchitis, on the ions of irritating substance (often particulate in	
SILICA WELDING FUMES & CHROMIUM FUME CHROMIUM FUME &	also been included in the criteria for diagnosis of disorder with rates related to the concentration of other hand, is a disorder that occurs as result of nature) and is completely reversible after exposi- production. The substance is classified by IARC as Group 3 NOT classifiable as to its carcinogenicity to hum Evidence of carcinogenicity may be inadequate	ng and the lack of minimal lympho of RADS. RADS (or asthma) follow of and duration of exposure to the f exposure due to high concentrati ure ceases. The disorder is chara 3: nans. or limited in animal testing.	cytic inflammation, without eosinophilia, have ving an irritating inhalation is an infrequent irritating substance. Industrial bronchitis, on the ions of irritating substance (often particulate in	
SILICA WELDING FUMES & CHROMIUM FUME CHROMIUM FUME & MOLYBDENUM FUME	also been included in the criteria for diagnosis of disorder with rates related to the concentration of other hand, is a disorder that occurs as result of nature) and is completely reversible after exposi- production. The substance is classified by IARC as Group 3 NOT classifiable as to its carcinogenicity to hum Evidence of carcinogenicity may be inadequate No significant acute toxicological data identified	ng and the lack of minimal lympho of RADS. RADS (or asthma) follow of and duration of exposure to the f exposure due to high concentrati ure ceases. The disorder is chara 3: hans. or limited in animal testing. in literature search.	ecytic inflammation, without eosinophilia, have wing an irritating inhalation is an infrequent irritating substance. Industrial bronchitis, on the ions of irritating substance (often particulate in acterised by dyspnea, cough and mucus	
SILICA WELDING FUMES & CHROMIUM FUME CHROMIUM FUME & MOLYBDENUM FUME Acute Toxicity	also been included in the criteria for diagnosis of disorder with rates related to the concentration of other hand, is a disorder that occurs as result of nature) and is completely reversible after exposi- production. The substance is classified by IARC as Group 3 NOT classifiable as to its carcinogenicity to hum Evidence of carcinogenicity may be inadequate No significant acute toxicological data identified	ng and the lack of minimal lympho of RADS. RADS (or asthma) follow of and duration of exposure to the f exposure due to high concentrati ure ceases. The disorder is chara as: anans. or limited in animal testing. in literature search. Carcinogenicity	cytic inflammation, without eosinophilia, have wing an irritating inhalation is an infrequent irritating substance. Industrial bronchitis, on the ions of irritating substance (often particulate in icterised by dyspnea, cough and mucus	
SILICA WELDING FUMES & CHROMIUM FUME CHROMIUM FUME & MOLYBDENUM FUME Acute Toxicity Skin Irritation/Corrosion Serious Eye	also been included in the criteria for diagnosis of disorder with rates related to the concentration of other hand, is a disorder that occurs as result of nature) and is completely reversible after exposi- production. The substance is classified by IARC as Group 3 NOT classifiable as to its carcinogenicity to hum Evidence of carcinogenicity may be inadequate No significant acute toxicological data identified	ng and the lack of minimal lympho of RADS. RADS (or asthma) follow of and duration of exposure to the f exposure due to high concentration ure ceases. The disorder is chara as: aans. or limited in animal testing. in literature search. Carcinogenicity Reproductivity	cytic inflammation, without eosinophilia, have ving an irritating inhalation is an infrequent irritating substance. Industrial bronchitis, on the ions of irritating substance (often particulate in icterised by dyspnea, cough and mucus	

Data available to make classification

SECTION 12 Ecological information

Toxicity

	Endpoint	Test Duration (hr)	Species	Value	Source
TALARC CrMo B2	Not Available	Not Available	Not Available	Not Available	Not Available
	Endpoint	Test Duration (hr)	Species	Value	Source
welding fumes	Not Available	Not Available	Not Available	Not Available	Not Available
	Endpoint	Test Duration (hr)	Species	Value	Source
	NOEC(ECx)	504h	Fish	0.52mg/l	2
iron oxide fume	LC50	96h	Fish	0.05mg/l	2
	EC50	72h	Algae or other aquatic plants	18mg/l	2
	EC50	48h	Crustacea	>100mg/l	2

	Endpoint	Test Duration (hr)		Species		Value	Source
	NOEC(ECx)	504h		Algae or other aquatic plants		0.05-3.7mg/l	4
manganese fume	LC50	96h		Fish		>3.6mg/l	2
	EC50	72h		Algae or other aquatic plants		2.8mg/l	2
	EC50	48h		Crustacea		>1.6mg/l	2
	Endpoint	Test Duration (hr)		Species		Value	Source
	NOEC(ECx)	504h		Crustacea		100mg/l	2
silica welding fumes	LC50	96h		Fish		>100mg/l	2
	EC50	72h		Algae or other aquatic plants		~250mg/l	2
	Endpoint	Test Duration (hr)	S	pecies	Val	ue	Sourc
	EC50(ECx)	48h	С	Crustacea	<0.	001mg/l	2
	LC50	96h	F	ïsh	0.1	06mg/L	4
chromium fume	EC50	72h	A	lgae or other aquatic plants	0.0	26-0.208mg/L	4
	EC50	48h	С	Crustacea	<0.	001mg/l	2
	EC50	96h	A	lgae or other aquatic plants	36r	ng/L	4
	Endpoint	Test Duration (hr)		Species		Value	Sourc
	NOEC(ECx)	48h		Algae or other aquatic plants		0.5-80mg/l	4
molybdenum fume	LC50	96h		Fish		211mg/l	2
	EC50	72h		Algae or other aquatic plants		26mg/l	2
	EC50	48h		Crustacea		130.9mg/l	2
Legend:	4. US EPA, Eco		a 5. ECE	egistered Substances - Ecotoxicolog ETOC Aquatic Hazard Assessment D Data 8. Vendor Data		•	ntic Toxici

DO NOT discharge into sewer or waterways.

Persistence and degradability

Ingredient	Persistence: Water/Soil	Persistence: Air	
	No Data available for all ingredients	No Data available for all ingredients	

Bioaccumulative potential

Ingredient	Bioaccumulation
	No Data available for all ingredients

Mobility in soil

Ingredient	Mobility
	No Data available for all ingredients

SECTION 13 Disposal considerations

Waste treatment methods

	Recycle wherever possible or consult manufacturer for recycling options.	
Product / Packaging	Consult State Land Waste Management Authority for disposal.	
disposal	Bury residue in an authorised landfill.	
	Recycle containers if possible, or dispose of in an authorised landfill.	

SECTION 14 Transport information

Labels Required

Marine Pollutant NO

HAZCHEM Not Applicable

Land transport (ADG): NOT REGULATED FOR TRANSPORT OF DANGEROUS GOODS

Air transport (ICAO-IATA / DGR): NOT REGULATED FOR TRANSPORT OF DANGEROUS GOODS

Sea transport (IMDG-Code / GGVSee): NOT REGULATED FOR TRANSPORT OF DANGEROUS GOODS

Transport in bulk according to Annex II of MARPOL and the IBC code

Not Applicable

Transport in bulk in accordance with MARPOL Annex V and the IMSBC Code

Product name	Group
welding fumes	Not Available
iron oxide fume	Not Available
manganese fume	Not Available
silica welding fumes	Not Available
chromium fume	Not Available
molybdenum fume	Not Available

Transport in bulk in accordance with the ICG Code

Product name	Ship Type
welding fumes	Not Available
iron oxide fume	Not Available
manganese fume	Not Available
silica welding fumes	Not Available
chromium fume	Not Available
molybdenum fume	Not Available

SECTION 15 Regulatory information

Safety, health and environmental regulations / legislation specific for the substance or mixture

welding fumes is found on the following regulatory lists	
International Agency for Research on Cancer (IARC) - Agents Classified by the IARC Monographs	International Agency for Research on Cancer (IARC) - Agents Classified by the IARC Monographs - Group 1: Carcinogenic to humans
iron oxide fume is found on the following regulatory lists	
Australia Standard for the Uniform Scheduling of Medicines and Poisons (SUSMP) - Schedule 4	Australian Inventory of Industrial Chemicals (AIIC) International Agency for Research on Cancer (IARC) - Agents Classified by
Australia Standard for the Uniform Scheduling of Medicines and Poisons	the IARC Monographs
(SUSMP) - Schedule 5 Australia Standard for the Uniform Scheduling of Medicines and Poisons	International WHO List of Proposed Occupational Exposure Limit (OEL) Values for Manufactured Nanomaterials (MNMS)
(SUSMP) - Schedule 6 manganese fume is found on the following regulatory lists	
Australia Hazardous Chemical Information System (HCIS) - Hazardous Chemicals	International WHO List of Proposed Occupational Exposure Limit (OEL) Values for Manufactured Nanomaterials (MNMS)
Australian Inventory of Industrial Chemicals (AIIC)	
silica welding fumes is found on the following regulatory lists	
Australia Hazardous Chemical Information System (HCIS) - Hazardous Chemicals	International WHO List of Proposed Occupational Exposure Limit (OEL) Values for Manufactured Nanomaterials (MNMS)
Australian Inventory of Industrial Chemicals (AIIC)	
chromium fume is found on the following regulatory lists	
Australian Inventory of Industrial Chemicals (AIIC)	International WHO List of Proposed Occupational Exposure Limit (OEL)
International Agency for Research on Cancer (IARC) - Agents Classified by the IARC Monographs	Values for Manufactured Nanomaterials (MNMS)

Australian Inventory of Industrial Chemicals (AIIC)

International WHO List of Proposed Occupational Exposure Limit (OEL) Values for Manufactured Nanomaterials (MNMS)

National Inventory Status

National Inventory	Status	
Australia - AIIC / Australia Non-Industrial Use	Yes	
Canada - DSL	Yes	
Canada - NDSL	No (iron oxide fume; manganese fume; silica welding fumes; chromium fume; molybdenum fume)	
China - IECSC	Yes	
Europe - EINEC / ELINCS / NLP	Yes	
Japan - ENCS	No (manganese fume; chromium fume; molybdenum fume)	
Korea - KECI	/es	
New Zealand - NZIoC	Yes	
Philippines - PICCS	Yes	
USA - TSCA	Yes	
Taiwan - TCSI	Yes	
Mexico - INSQ	No (silica welding fumes)	
Vietnam - NCI	Yes	
Russia - FBEPH	Yes	
Legend:	Yes = All CAS declared ingredients are on the inventory No = One or more of the CAS listed ingredients are not on the inventory. These ingredients may be exempt or will require registration.	

SECTION 16 Other information

Revision Date	01/11/2019
Initial Date	31/07/2017

SDS Version Summary

Version	Date of Update	Sections Updated
3.1	01/08/2017	Spills (major), Use
4.1	01/11/2019	One-off system update. NOTE: This may or may not change the GHS classification

Other information

Classification of the preparation and its individual components has drawn on official and authoritative sources as well as independent review by the Chemwatch Classification committee using available literature references.

The SDS is a Hazard Communication tool and should be used to assist in the Risk Assessment. Many factors determine whether the reported Hazards are Risks in the workplace or other settings. Risks may be determined by reference to Exposures Scenarios. Scale of use, frequency of use and current or available engineering controls must be considered.

Definitions and abbreviations

- PC-TWA: Permissible Concentration-Time Weighted Average
- PC-STEL: Permissible Concentration-Short Term Exposure Limit

IARC: International Agency for Research on Cancer

- ACGIH: American Conference of Governmental Industrial Hygienists
- STEL: Short Term Exposure Limit
- TEEL: Temporary Emergency Exposure Limit。
- IDLH: Immediately Dangerous to Life or Health Concentrations
- ES: Exposure Standard
- OSF: Odour Safety Factor
- NOAEL :No Observed Adverse Effect Level
- LOAEL: Lowest Observed Adverse Effect Level
- TLV: Threshold Limit Value
- LOD: Limit Of Detection
- OTV: Odour Threshold Value BCF: BioConcentration Factors

BEI: Biological Exposure Index AIIC: Australian Inventory of Industrial Chemicals DSL: Domestic Substances List NDSL: Non-Domestic Substances List IECSC: Inventory of Existing Chemical Substance in China EINECS: European INventory of Existing Commercial chemical Substances ELINCS: European List of Notified Chemical Substances NLP: No-Longer Polymers ENCS: Existing and New Chemical Substances Inventory KECI: Korea Existing Chemicals Inventory NZIoC: New Zealand Inventory of Chemicals PICCS: Philippine Inventory of Chemicals and Chemical Substances TSCA: Toxic Substances Control Act TCSI: Taiwan Chemical Substance Inventory INSQ: Inventario Nacional de Sustancias Químicas NCI: National Chemical Inventory FBEPH: Russian Register of Potentially Hazardous Chemical and Biological Substances

This document is copyright.

Apart from any fair dealing for the purposes of private study, research, review or criticism, as permitted under the Copyright Act, no part may be reproduced by any process without written permission from CHEMWATCH.

TEL (+61 3) 9572 4700.

